# Technical Information Silopilot FMM50

Electromechanical Level Measuring System



The simple and easy-to-understand level meter for all bulk solids and fluids

#### Application

- Measuring principle independent of physical properties like mass density
- Measuring of level in bunkers and silos with powdered, fine or coarse grain bulk solids or in vessels containing liquids

#### Device properties

- Level measurements up to 90 m
- Process temperatures up to +230 °C (+446 °F)
- Process pressure up to 300 kPa (3 bar) absolute
- Use in aggressive atmospheres, for example acidic or caustic vapours possible
- Separation layer detection in fluids possible with suitable sensing weights

#### Your benefits

- Suitable for process conditions where typical ultrasonic or radar level meter fail to work dependably
- Precise detection of the level (accuracy of ±5 cm or ±1 pulse)
- Compact transmitter with 0/4 20 mA current output as well as further free programmable signal outputs (for example counter pulse)
- Quick menu-quided local operation using a 4-line text display
- Fully electronic digital minimum fail-safe control, therefore no running down of the sensor weight into the silo outlet and no risk to the conveying systems



### Table of contents

<b>Document information</b>
Function and system design4Measuring principle4Measuring system4Safety5
Input6Measured variable6Measuring range6Blocking distance7Input signal7Operating frequency7
Output8Output signal8Signal on alarm8Load8Linearisation9
Power supply10Terminal assignment10Supply voltage11Power consumption11Power supply failure11Potential equalization11Terminals11Cable entries11Cable specification11
Performance characteristics12Measured value resolution12Maximum measured error12Influence of ambient temperature12
Installation13Mounting location13Orientation14Installation instructions14Selection sensing weights14Special installation15
Environment16Ambient temperature range16Storage temperature16Degree of protection16Electromagnetic compatibility (EMC)16
Process17Process temperature range17Process pressure range17Heating17Vibrations17

Mechanical construction	
Dimensions	20
Materials Process connection	
Operability	21
Derating concept	21
ocal operation	
anguages	22
Certificates and approvals	22
CE approval	
Ex approval	
Other standards and guidelines	22
Ordering information	23
Product structure	
Scope of delivery	23
Jser-specific settings	23
Accessories	25
Devcie-specific accessories	
Devcie-specific tools	
Oocumentation	35
Standard documentation	
Supplementary device-dependent documentation	35

### **Document information**

#### **Document conventions**

#### Safety symbols

Symbol	Meaning
<b>▲</b> DANGER	<b>DANGER!</b> This symbol alerts you to a dangerous situation. Failure to avoid this situation will result in serious or fatal injury.
<b>▲</b> WARNING	WARNING! This symbol alerts you to a dangerous situation. Failure to avoid this situation can result in serious or fatal injury.
<b>A</b> CAUTION	CAUTION!  This symbol alerts you to a dangerous situation. Failure to avoid this situation can result in minor or medium injury.
NOTICE	NOTICE! This symbol contains information on procedures and other facts which do not result in personal injury.

#### **Electrical symbols**

Symbol	Meaning	Symbol	Meaning
	Direct current	~	Alternating current
	Protective ground connection A terminal which must be connected to ground prior to establishing any other connections.	<del> </del>	Ground connection A grounded terminal which, as far as the operator is concerned, is grounded via a grounding system.

#### Symbols for certain types of information

Symbol	Meaning
<b>✓</b>	Allowed Indicates procedures, processes or actions that are allowed.
<b>V</b>	Preferred Indicates procedures, processes or actions that are preferred.
×	Forbidden Indicates procedures, processes or actions that are forbidden.
i	Tip Indicates additional information.
	Reference to documentation Refers to the corresponding device documentation.
A=	Reference to page Refers to the corresponding page number.
	Reference to graphic Refers to the corresponding graphic number and page number.
	Visual inspection


#### Symbols in graphics

Symbol	Meaning	Symbol	Meaning
1, 2, 3	Item numbers	1., 2., 3	Series of steps
A, B, C	Views	A-A, B-B, C-C	Sections
<u>/EX</u>	Hazardous area	×	Safe area (non-hazardous area)

### Function and system design

#### Measuring principle

A measuring tape, loaded with a sensing weight, is lowered into the bunker or silo (2). When the weight meets the surface of the product the tension on the measuring tape is relaxed (3) and this is detected by the device electronics.



■1 Measuring principle

The measured value is transmitted to the 0/4 - 20 mA current output. The sensing weight now runs back up to the start position (1) and the measured value is retained until the next measurement is performed.


During the entire measuring process (lowering and hoisting of the sensing weight) the device can also transmit pulses (relay output) corresponding to the length of the measuring tape, which can be recorded by a control unit or by an electromechanical counter.

Both individual measurements and periodic measurement sequences can be performed. The measurement can then be initiated manually (for example external start button) or periodically (for example programmed function of the device).

The unit is delivered with default values for the maximum measuring range according to the unit configuration (see ordering information). The menu-guided programming using the 4-line text display assures easy and fast adjustment to the bunker or silo geometry.

#### Measuring system

The FMM50 is a compact transmitter with integrated microprocessor-controlled electronics, various in- and outputs ( $\rightarrow \blacksquare 7, 8$ ) are provided. The device can be adapted to different applications by choosing one of the suitable sensing weights ( $\rightarrow \blacksquare 14$ ).



■2 FMM50 with open electronic side

#### Type of housing and materials

Compact, Aluminium, optional coated

#### Sensing weights ( $\rightarrow$ $\cong$ 14) and materials

- Steel, optional with umbrella Polyester
- Stainless steel 316TI, optional with umbrella Polyester
- Plastic PVC

#### Configuration

Operation via 4-line local display with plain and help texts

#### Safety

We only provide a warranty if the device is installed and used as described in the Operating Instructions. The device is equipped with security mechanisms to protect it against any inadvertent changes to the device settings.

Security measures in line with operators' security standards and designed to provide additional protection for the device and device data transfer must be implemented by the operators themselves.

### **Input**


#### Measured variable

#### Measured process variables

The measured value is the distance between the flange of the Silopilot minus a blocking distance and the surface of the product.

#### Calculated process variables

The filling level is computed taking into account the fixed given calibration values, for example the empty calibration (height of the silo). The filling level can be converted to other values as desired, for example volume or mass, by the application of linearization.



■3 Adjustment values of the FMM50

#### Measuring range

Max. 90 m

The highest measurable point is given by the blocking distance (see figure "Measuring principle") plus a minimum descent length of 20 cm. This maximum length must be considered on input of the maximum measuring range (full calibration).

#### Blocking distance

The blocking distance (BD) depends on the wiper length and the selected sensing weight.

Sensing weight	Wiper 230 mm	Wiper 500 mm	Wiper 1000 mm
B, C, D, E, L	0.80 m	1.10 m	1.60 m
G	1.20 m	1.50 m	2.00 m
J	0.86 m	1.16 m	1.66 m
M, N	0.65 m	0.95 m	1.45 m

#### NOTICE

The individual value for the blocking distance is preset on delivery and only needs to be adjusted when changing the sensing weight for example, the relevant input option can be found in the menu.

#### Input signal

Remote operation possible via two inputs, each input can be assigned as either active or passive and is therfore usable.



The device is available with an optional external start button ( $\rightarrow \cong 21$ ), which is connected to the passive signal input 1.

#### **Active inputs**

- Connection of an external voltage
- Input voltage range: 12...24 VDC
- Input polarity: Normally open or normally closed
- Start pulse length: min. 200 ms

#### Passive inputs

- Connection of an external command device, for example switch/button, relay contact
- Contact rating: max. 0.3 W / 30 VDC
- Input polarity: Normally opened or normally closed
- Start pulse length: min. 200 ms

#### Operating frequency

#### Measuring cycle

Min. 1 minute

#### NOTICE

- Please observe the minimum time (TM) for one measuring cycle with the device according to the measuring range and the ambient temperature ( $\rightarrow \boxtimes 12$ ).
- This minimum time must be taken into account in all types of measuring.
- We recommend not to go below a time of 5 minutes for one measuring cycle.

#### Tape run speed

The speed of the tape is between 0.21 m/s and 0.35 m/s.

### Output


#### Output signal

#### Current output

- 0/4-20 mA (active, 0-20 mA / 4-20 mA programmable)
- max. 22 mA

#### Relay output

- Number: 2 (optional 6)Contact rating: 250 VAC, 6 A
- Contact material: silver-cadmium-oxide, gold-flashed



#### Signal on alarm

Malfunction signal can be called up via the following interfaces.

#### Local indication

- Error symbol
- Error code with text indication

#### **Current output**

- Minimum: minimum current value <= 3.6 mA (4-20 mA) or 0 mA (0-20 mA)
- Maximum: maximum current value + 10% (≈22 mA)
- Programmable: current value 0-22 mA
- Hold: last valid current value

#### Relay output


Alarm function

Load

Load of the current output: max.  $600\,\Omega$ 

#### Linearisation


The linearisation function of the device facilitates conversion of the measured value into engineering units such as cubic metres or hectolitres. If the filling level is not uniformly proportional to the volume within the set measuring range, then a linearization curve can be entered using a maximum of 32 reference values.



■4 Linearisation

### Power supply

#### Terminal assignment



 $\blacksquare 5$  Terminals of the FMM50

Ordering code	Te	erminal assign	ment
Power supply -	1.1	L1 (~)	Power supply
option 1, 2	1.2	N (~)	
	1.3	PE ( ± )	
Output - option A, B	2.1		Relay 1
	2.2		
	2.3		
	2.4		Relay 2
	2.5		
	2.6		
Output - option <b>B</b>	2.7		Relay 3
	2.8		
	2.9		
	2.10		Relay 4
	2.11		
	2.12		
	2.13		Relay 5
	2.14		
	2.15		
	2.16		Relay 6
	2.17		
	2.18		
without	3.1	(+)	Input 1, active
	3.2	(-)	
	3.3	(+)	Input 2, active
	3.4	(-)	
	3.5		Input 1, passive
	3.6		
	3.7		Input 2, passive
	3.8		
	3.9	(+)	Current output
	3.10	(-)	

The rest position matches with the position of the relays without power supply, this represents the alarm condition if the function "alarm" is selected.

#### Supply voltage ■ 180-253 VAC, 50/60 Hz (ordering code "power supply", option 1) ■ 90-127 VAC, 50/60 Hz (ordering code "power supply", option 2) NOTICE • When using the public powers supply, install an easily accessible power switch in the proximity of the instrument. Mark the power switch as a disconnector for the instrument (EN/IEC 61010). • You should use a fuse to protect the power supply against short-circuit. Power consumption ■ Max. 230 VA (ordering code "ambient temperature", option A or C) ■ Max. 250 VA (ordering code "ambient temperature", option **B** or **D**) Power supply failure • Configuration is retained in the device memory. • The current error is shifted into the last error function. Potential equalization Requirements • The potential matching should be connected up to the outer grounding terminal of the device. • For an optimum electromagnetic compatibility, the potential matching line should be as short as possible. ■ The recommended minimum cable cross-section is 2.5 mm². • The device's potential matching should be included in the local potential matching. For devices intended for use in hazardous locations, please observe the guidelines in the ${\tt Ex}$ documentation (XA). **Terminals** ■ Max. 2.5 mm<sup>2</sup> (power supply) ■ Max. 1.5 mm² (signal inputs, relay outputs, current output) Cable entries ■ M25 x 1.5 • Cable gland non-hazardous area: - Material: plastic - Color: grey - Clamping range: 9...17 mm Cable gland ATEX: - Material: plastic - Color: black

#### Cable specification

■ Minimum requirement: cable temperature range ≥ ambient temperature

4 pieces (ordering code "additional equipment", option 1)
3 pieces (ordering code "additional equipment", option 2)

- Clamping range: 9...13 mm

Number:

• Standard installation cable is sufficient for signal inputs, relay outputs and current output.

### **Performance characteristics**

#### Measured value resolution


•  $\pm$  5 cm or  $\pm$  1 pulse (irrespective of the selected measuring range)

#### Maximum measured error

The maximum measured error is identical with the measured value resolution ( $\pm$  5 cm or  $\pm$  1 pulse, irrespective of the selected measuring range).

### Influence of ambient temperature

- Please observe the minimum time  $(T_M)$  for one measuring cycle with the device according to the measuring range (MR) and the ambient temperature  $(T_A)$ .
- This minimum time must be taken into account in all types of measuring.



**№**6 *Influence of ambient temperature* 


#### NOTICE

We recommend not to go below a time of 5 minutes for one measuring cycle.

#### Installation

#### Mounting location


- Select a mounting location on the bunker or silo such that product falling inside during filling, or accumulations of product collapsing inward, cannot cover the sensing weight nor damage the measuring tape.
- The measuring path should not pass too close to any internal fixtures or struts, so that the measuring tape will not brush against them if the sensing weight swings around.
- Select the length of the tape wiper such that the sensing weight is outside of the mounting flange.



■ 7 Mounting location - Distances

#### NOTICE

Take due account of the shape and location of the product inflow cone and the outflow funnel within the vessel.



■8 Mounting location - Measurement processing

#### Orientation

The device is best mounted on a counter flange DN100 PN16 (connection dimensions according to EN 1092-1) or a flange having the same connection dimensions. The counter flange must be mounted exactly horizontal so that the device can also be mounted horizontally onto it (maximum angle of inclination 2°). There are suitable process adapters for the device available ( $\Rightarrow \boxtimes 25$ ).



A suitable installation aid (bubble level) can be found inside the devices with coated housing which, with the electronics cover opened, can be used for alignment.

#### Installation instructions

- When installing outside, fit the protection hood (available as spare part) or install a weather protection roof.
- Normal weights, umbrella weights and bag weights (→ 

  18) can be passed through the DN100 mounting flange into the bunker/silo. When using larger sensing weights, such as cage weights, bell weights, floats and some bag-type weights, access provision must be present in the construction of the bunker/silo for installation of these weights.
- When installing in bunkers/silos with heavy dust loadings, a slight positive pressure can be generated at the device by connecting a compressed air line to its mounting flange (airflow quantity as required). There is a G1/4 female connection provided for this purpose at the device flange.

#### Selection sensing weights

When selecting the sensing weight the following points should be considered:

- The sensing weight may not sink into the product nor be diverted by contact with the product cone during the measuring procedure.
- The sensing weight must be suited for the chemical characteristics of the product and the temperature within the bunker/silo.
- Special types for your individual applications are available on request.
- Dimensions  $\rightarrow$  🗎 18

#### Normal weight (ordering code "sensing weight", option B or C)

- Application: For coarse bulk solids, for example coals, ores or stones and granulates.
- Material: Steel or stainless steel
- Weight: 3.5 kg
- The spike can be taken off.

#### **Umbrella weight** (ordering code "sensing weight", option **D** or **E**)

- Application: For very light and loose bulk solids, for example flour or coal-dust. The umbrella weight has a large square surface area which prevents it from sinking deeply into the product.
- Materials: Steel or stainless steel, polyester
- Weight: 3.9 kg (option D) / 3.8 kg (option E)
- Maximum permissible temperature: +150 °C (+302 °F)
- When folded closed, the weight can be passed through the DN100 mounting flange into the bunker.
- The umbrella has a large, square area, preventing it from being immersed in the bulk solids.



#### Bag weight (ordering code "sensing weight", option G)

- Application: In bunkers to which for example mills are connected down-stream. The bag contains whichever product is contained within the bunker.
- Materials: Bag made of polyester, all metal parts made from stainless steel.
- Weight: 0.25 kg (empty) / 3.5 kg (filled)
- Maximum permissible temperature: +150 °C (+302 °F)
- Bind the bag closed at the top so that the contents cannot fall out if the bag tips over on the slope of a product cone.



#### Cage weight (ordering code "sensing weight", option J)

- Application: For fine bulk solids in silos with relatively small outlet openings that must not be blocked by a sensing weight which has broken free. Also suitable for high temperatures for which a bag may not be used.
- Material: Stainless steel 316Ti
- Weight: 3.5 kg
- The weight could become lodged over the product outlet, but would allow the bulk solid to pass through. Since the cage weight cannot enter a conveyor system (for example cellar wheel feeder or screw conveyor), no damage can result.

#### Bell weight (ordering code "sensing weight", option L)

- Application: For light and loose bulk solids; especially where higher temperatures and particular characteristics preclude the use of an umbrella weight.
- Material: Stainless steel 316Ti
- Weight: 4.3 kg



#### Oval float (ordering code "sensing weight", option M or N)

- Application: For liquids, for example fuel oil, also for granulates.
- Material: Hard PVC (maximum permissible temperature: 0...+60 °C (+32...+140 °F)) or stainless steel 316Ti
- Weight: The float must be filled with product to a total weight of 3.5 kg.
- Use of the oval float made of hard PVC in the "Dust ignition-proof" version is not permitted!
- Utilization of the oval float is permissible for process pressures 0.8...1.1 bar absolute.





If the bunker/silo has a downstream crushing or milling system, we recommend using the electrical signal function "tape breakage" or the use of a cage weight to avoid damaging the system in the event of the sensing weight breaking free.

#### Special installation

#### Protection hood

A minimum space of 400 mm above the unit is necessary to remove the protection hood ( $\rightarrow \triangleq 25$ ).

#### **Environment**

## Ambient temperature range

#### Measuring device

Ambient temperature at the measuring device:

- -20...+70 °C (-4...+158 °F)
- -40...+70 °C (-40...+158 °F) using the self-regulating device heater

#### Local display

- -20...+70 °C (-4...+158 °F)
- The readability of the display may be impaired at temperatures outside the temperature range.

#### If operating outdoors:

Avoid direct sunlight, particularly in warm climatic regions.



Weather protection covers can be ordered from Endress+Hauser: see "Accessories" section  $\rightarrow$   $\cong$  25

#### Storage temperature

-40...+80 °C (-40...+176 °F)

#### Degree of protection

- IP 67 (with closed housing)
- IP 65 (with closed housing and when using the external start button)
- IP 20 (with open housing)

## Electromagnetic compatibility (EMC)


- Interference emission in accordance with EN 61326, class B operating equipment
- Interference immunity in accordance with EN 61326, Appendix A (industrial sector)
- Normal installation cable is sufficient for the wiring.

#### **Process**

#### Process temperature range

- -20...+70 °C (-4...+158 °F), ordering code "process temperature", option  $\bf 1$
- -20...+150 °C (-4...+302 °F), ordering code "**process temperature**", option **2**
- -20...+230 °C (-4...+446 °F), ordering code "**process temperature**", option **3**

The maximum process temperature at the unit from the bottom of the adaptor flange upwards is +70 °C (+158 °F). In the presence of higher process temperatures in the vicinity of the mounting location, suitable installation provisions must be utilized to assure these temperature quidelines.



■9 Permissible ambient temperatures at the FMM50

An extension for the process connection can be used to separate the device from the higher process temperatures. The maximum allowed temperature of  $+70\,^{\circ}\text{C}$  ( $+158\,^{\circ}\text{F}$ ) can be met through this. The required length of the connection nozzle is dependant on the actual process and ambient conditions.

- We recommend the following minimum length of the process connection nozzle:
  - Min. 500 mm at process temperatures up to 150 °C (+302 °F)
  - Min. 1000 mm at process temperatures up to 230 °C (+446 °F)
- Suitable process adapter extensions with a length of 790 mm for use with 1000 mm wiper are available as accessory ( $\rightarrow \triangleq 25$ ).
- When using process nozzles longer than 230 mm (length of the standard wiper), optional larger wipers should be considered (see order code).
  - Alternatively, the length of the chain between tape border and sensing weight can be increased, corresponding parts are available as an accessory (→ \( \begin{align\*} \exists 25 \).

#### Process pressure range

- 80...110 kPa (0.8...1.1 bar) absolute (ordering code "process pressure", option 1)
- 80...300 kPa (0.8...3.0 bar) absolute (ordering code "process pressure", option 2)

#### Heating

It is recommended that at ambient temperatures below 0  $^{\circ}$ C (+32  $^{\circ}$ F) a device with integrated heater is choosen (ordering code "Ambient temperature", option **B** and **D**).


#### **Vibrations**

Due to the layout, the device should not be exposed to vibration. The pendular motion of the motor combined with vibrations can lead to erratic triggering of the tape switch and therefore to faulty measurements.

### Mechanical construction

#### Dimensions

#### Housing




**■**10 Housing dimensions

The wiper length (L) depends on the selected maximum nozzle height:

Ordering code "maximum connection height; wiper"	L
A, B	225 mm (8.86 in)
C, D	515 mm (20.28 in)
E, F	1015 mm (39.96 in)


- Ordering code "process pressure", option 1: 196 mm (7.72 in)
   Ordering code "process pressure", option 2: 211 mm (8.31 in)

#### **Process connection**




■ 11 Dimensions of the process connection


#### Sensing weights



 $\blacksquare 12~$  Dimensions of sensing weights - Standard (with umbrella) and medium bag



■13 Dimensions of sensing weights - Bell and cage



■ 14 Dimensions of sensing weights - Oval float

#### Weight

- 22...28 kg (depends on the selected type of device, without sensing weight)
- Sensing weights  $\rightarrow = 14$

#### Materials

- Housing: Aluminum (optional coated, RAL 5012 and RAL 7035)
- Wiper:
- Alu/Steel or
- Stainless steel
- Tape: Stainless steel
- Sensing weights  $\rightarrow$  🗎 14

#### **Process connection**

- Flange
- $\blacksquare$  Hole dimensions DN100 PN16 according to EN 1092-1

### Operability

#### Operating concept

#### Operator-oriented menu structure for user-specific tasks

- Commissioning
- Operation
- Diagnostics
- Expert level

#### Quick and safe commissioning

Menu guidance with brief explanations of the individual parameter functions

#### Reliable operation

- Operation in the following languages: English, German, French, Japanese
- Help texts in the selected language


#### Efficient diagnostics increase measurement availability

- Display of the current and the last error
- Help texts for every occuring error
- Various simulation options

#### Local operation

#### Operating elements

- Local operation (parameterization) with 3 push buttons: □, ±, ₺
- Local operation (start measuring) with one push button (1), optional with external start button (2), ordering code "additional equipment", option 2




■15 Manual start of measurement

- 1 Internal start push button
- 2 External start push button (optional)

#### Display elements

- 4-line display
- 20 characters per line
- $\ \ \, \blacksquare$  Display contrast adjustable by using a key combination
- Display of measurand numeric and graphic
- Permitted ambient temperature for the display: -20...+60 °C (-4...+140 °F), the readability of the display may be impaired at temperatures outside the temperature range.



**■**16 *Display and operation elements* 

#### Languages

- English
- German
- French
- Japanese

### Certificates and approvals

#### CE approval

The measuring system is in conformity with the statutory requirements of the applicable EU Directives. These are listed in the corresponding EU Declaration of Conformity along with the standards applied.

Endress+Hauser confirms successful testing of the device by affixing to it the CE mark.

#### Ex approval

The measuring device is certified for use in hazardous areas and the relevant safety instructions are provided in the separate "Safety Instructions" (XA) document. Reference is made to this document on the nameplate.



The separate Ex documentation (XA) containing all the relevant explosion protection data is available from your Endress+Hauser sales center and as a download from <a href="https://www.endress.com">www.endress.com</a>.

### Other standards and guidelines

■ EN 60529

Degrees of protection by housing (IP code)

■ EN 61010-1

Protection Measures for Electrical Equipment for Measurement, Control, Regulation and Laboratory Procedures.

■ IEC/EN 61326

Interference emissions (Equipment class B) and interference resistance (Attachment A - industrial systems)

■ IEC/EN 60079-0

Explosive atmospheres - Part 0: Equipment - General requirements

■ IEC/EN 60079-31

Explosive atmospheres - Part 31: Equipment dust ignition protection by enclosure "t"

### **Ordering information**

#### **Product structure**

Detailed ordering information is available from the following sources:

- In the Product Configurator on the Endress+Hauser website: www.endress.com → Select your country → Products → Select measuring technology, software or components → Select the product (picklists: measurement method, product family etc.) → Device support (right-hand column): Configure the selected product → The Product Configurator for the selected product opens.
- From your Endress+Hauser Sales Center: www.addresses.endress.com

#### i

#### Product Configurator - the tool for individual product configuration

- Up-to-the-minute configuration data
- Depending on the device: Direct input of measuring point-specific information such as measuring range or operating language
- Automatic verification of exclusion criteria
- Automatic creation of the order code and its breakdown in PDF or Excel output format

#### Scope of delivery

The scope of delivery includes a minimum of the FMM50 in one cardboard box. Depending on the ordering code the following additional parts are supplied:

- Sensing weight (option **J**, **L** and **M** in one separate cardboard box)
- Wiper extension 500/1000 mm in one separate cardboard box

#### **User-specific settings**

As a service, the device can be programmed according to the customers specification during assembly, in this case the following form must be completed and added to the order.

# User-specific settings

# Endress+Hauser 3



People for Process Automation

The order option for Silopilot FMM50 with user-specific settings requires that all necessary parameters and
options are mentioned. Whereever informations are missing, default values will be used. This completed form
must be supplied with every order.

The order option options are men must be supplied	tione	d. Wr	ieree	ver ii				•			_	-						•	parameters and nis completed for
Order code: <b>F</b> I	MM5	50 -								$\top$				Τ			]		
Settings basic set	un, dis	splay :	and sy	stem	nara	met	ers										_		
001 empty calibr.		ıll calibi			meas.			21 tim	e inter	val	02	22 time unit 023 normal						short	024 service interv.
m/ft/in		m/	m/ft/in single cycle				1 10001				□ h □ normal □ short					ıl			
028 run up length	060 la	ınguage	9	061	back to	o hor	ne 06	32 no.	decin	nals	08	0 tag	no.		083	dista	anc	e unit	
m/ft/in	□ Eng □ Deu □ Fran □ 二ホソ	tsch içais		(defa	nult: 10	s 0)	0	□ X □ X.X			_ (n	(max. 16 digits)			□ m □ ft □ in				
Settings inputs an	d curi					_												ı	
010 input 1		011 p	olarity	input	1	C	)12 inp	out 2				013	polar	ity in	put 2	2			
<ul><li>□ not used</li><li>□ bolting</li><li>□ start measurement</li></ul>	nt		contac				<b>not u</b> boltin start ≀	g	ıremei	nt		□ NC							
030 current mode		031 (	)/4 mA	value		C	32 20	mA va	alue			033	curre	nt ra	nge				
□ <b>normal</b> □ magnify			[(	)56]				[0	56]			□ <b>4-20 mA</b> □ 0-20 mA							
Settings relay out	puts																		
014 relay 1	01 <i>A</i>	A relay	2		01B r	elay	3		01C	relay	y 4	01D relay 5							01E relay 6
□ alarm □ service interval □ counter pulses □ reset pulse □ running up □ top position □ measuring □ threshold □ band return				vice inter et pu ning posi asur eshol	ce interval cer pulses counter pulse counter					pulses							□ alarm □ service interval □ counter pulses □ reset pulse □ running up □ top position □ measuring □ threshold □ band return		
015 pulse value	016	pulse	length		017 li	mit v	/alue		018	hyste	eres	is	(	019	rese	t puls	e		
(default: 1)	(de	fault: 50	ms (default: 60)				6	(defa	ult: 3	3)	%(default: 300)					_ m	s		
Safety settings an											- 1								
040 output on alarm	1	041 (	output o	on alai	rm	10	)42 sa	tety di	stance	;	_	043	secu	rity d	listar	ice			in security distance
□ MIN (0/3.6mA) □ MAX (22mA) □ hold □ user-specific	mA			-	[083]				[083]						□ w □ al	<b>arning</b> arm			
045 in safety distance 050 level/volume				C	)51 line	eariza	tion			056 customer unit						057	max. scale		
□ warning □ alarm □ ullage CU □ level DU □ ullage DU				☐ linear☐ manually *1  *1 you need to enter manually a linearization curve			,	□ % □ ft³ □ kg □ m □ t □ ft □ m³ □ in						[056]					
Note:																			

 $\blacksquare$  The bold marked options are the default values.

 $\blacksquare$  Settings like "\_\_\_\_\_ [123]" relate to the option you select in function 123.

ad042000en/07.17

#### Accessories

Various accessories, which can be ordered with the device or subsequently from Endress+Hauser, are available. Detailed information on the order code in question is available from your local Endress+Hauser sales center or on the product page of the Endress+Hauser website: www.endress.com.

#### Devcie-specific accessories


#### Protection hood

A protective hood is available for mounting the measuring device outdoors.


Order code: 52027964Material: Stainless steel 304

■ Weight: 7.5 kg

■ The delivery contains suitable mounting bolts.



■17 Protection hood




#### Process adapter extension

If process temperatures are between +150 °C (+302 °F) and +230 °C (+446 °F), the following process adapter extensions can be used to reduce the temperature when using the 1000 mm wiper extension:

Order code: 52028083Material: Stainless steel 316Ti

■ Weight: 16 kg

• The delivery contains four suitable bolts and nuts to secure the measuring device to the process adapter extension.



 $\blacksquare 18$  Process adapter extension

#### Adapter flange

The following adapter flanges can be used to adapt to existing process connections:


■ Order code:

71301820	DN150, PN16, EN1092-1, stainless steel 316Ti
71301821	DN150, PN16, EN1092-1, steel
71301822	DN200, PN16, EN1092-1, stainless steel 316Ti
71301824	DN200, PN16, EN1092-1, steel
71301811	6", 150lbs, ASME B16.5, stainless steel 316Ti
71301815	6", 150lbs, ASME B16.5, steel
71301816	8", 150lbs, ASME B16.5, stainless steel 316Ti
71301817	8", 150lbs, ASME B16.5, steel

■ Dimensions (mm/in) and weights:

	А	В	С	D	Weight
71301820	8x	M16	22/0.87	285/11.22	9 kg
71301821	22/0.87	1/110	22/0.07	203/11.22	9 Kg
71301822	12x	M16	24/0.94	340/13.4	15 kg
71301824	22/0.87				
71301811	8x	UNC 5/8"	25.4/1	279.4/11	10 kg
71301815	22.4/0.88				
71301816	8x	UNC 5/8"	28.6/1.13	342.9/13.5	18 kg
71301817	22.4/0.88				

• The delivery contains four suitable nuts to secure the measuring device to the adapter flange.



■19 Adapter flange

The adapter flange is mounted between the process connection of the device and the application. As the flange is not very high, the clearance needed for the device is only marginally increased.

#### Adapter flange with studs for higher pressure ratings

The following adapter flanges can be used to adapt to existing process connections:


■ Order code:

71301826	DN100, PN25/40, EN1092-1, stainless steel 316Ti
71301829	DN100, PN25/40, EN1092-1, steel
71301831	4", 300lbs, ASME B16.5, stainless steel 316Ti
71301833	4", 300lbs, ASME B16.5, steel
71301834	4", 600lbs, ASME B16.5, stainless steel 316Ti
71301835	4", 600lbs, ASME B16.5, stainless steel

■ Dimensions (mm/in) and weights:

	A	В	С	D	Weight
71301826	8x M22	M16	25/0.98	235/9.25	7 kg
71301829	OX IVIZZ				
71301831	8x UNC 3/4"	UNC 5/8"	31.8/1.25	254/10	11 kg
71301833	8X UNC 3/4				
71301834	8x UNC 7/8"	UNC 5/8"	38.1/1.5	273.1/10.75	16 kg
71301835	8X UNC 778				

• The delivery contains four suitable nuts to secure the measuring device to the adapter flange.



 $\blacksquare 20$  Adapter flange with studs for higher pressure ratings


The adapter flange is mounted between the process connection of the measuring device and the application.

#### Process adapter as replacement for the standard adapter

The standard process adapter can be replaced by one of the following to adapt to existing process connections:

■ Order code:

71301870 150lbs, RF 4", ASME, Aluminium 71301872 150lbs, RF 4", ASME, Aluminium coated



 $\blacksquare 21$  Process adapter as replacement for the standard adapter

The standard process adapter ( $\rightarrow$   $\cong$  18) can be easily replaced by releasing four screws.

#### Process adapters for smaller nominal diameters


The following process adapters can be used to adapt to existing process connections with smaller nominal diameters (< DN100):

■ Order code: 71301837 DN50, PN16, EN1092-1, stainless steel 316Ti 71301839 DN50, PN16, EN1092-1, steel 71301841 DN65, PN16, EN1092-1, stainless steel 316Ti 71301843 DN65, PN16, EN1092-1, steel 71301844 DN80, PN16, EN1092-1, stainless steel 316Ti 71301857 DN80, PN16, EN1092-1, steel 71301858 2", 150lbs, ASME B16.5, stainless steel 316Ti 2", 150lbs, ASME B16.5, steel 71301859 71301861 3", 150lbs, ASME B16.5, stainless steel 316Ti 3", 150lbs, ASME B16.5, steel 71301864 71301867 4", 150lbs, ASME B16.5, stainless steel 316Ti 71301868 4", 150lbs, ASME B16.5, steel

■ Dimensions (mm/in) and weights:

	А	В	С	D	Е	Weight
71301837	400/	54,5/	125/	165/	18/	10.5 kg
71301839	15.75	2.15	4.92	6.50	0.71	10.5 Kg
71301841	400/	70,3/	145/	185/	18/	11 1.0
71301843	15.75	2.77	5.71	7.28	0.71	11 kg
71301844	200/	82,5/	160/	200/	20/	10 1.0
71301857	7.87	3.25	6.30	7.87	0.79	10 kg
71301858	420/	52,6/	120,7/	152,4/	19,1/	111.0
71301859	16.54	2.07	4.75	6.00	0.75	11 kg
71301861	220/	78/	152,4/	190,5/	23,9/	11 5 1.0
71301864	8.66	3.07	6.00	7.50	0.94	11.5 kg
71301867	128/	102,4/	190,5/	228,6/	23,9/	12 5 1.0
71301868	5.04	4.03	7.50	9.00	0.94	12.5 kg

<sup>■</sup> The delivery contains four suitable screws with nuts to secure the measuring device to the process adapter.



 $\blacksquare 22$  Process adapters for smaller nominal diameters

#### **NOTICE**

To prevent incorrect measurements if the sensing weight swings, the lower edge of the wiper should protrude out of the reduced area (diameter  ${\bf B}$ ).

#### Process adapter with spray water cleaning


The following process adapter can be used with spray water cleaning to prevent any damage from chemical substances that can enter the measuring device via the measuring tape:

■ Order code: 71301886

■ Material: Stainless steel 316Ti

■ Weight: 15 kg

• The delivery includes four suitable screws with nut to secure the measuring device to the process adapter.



**■**23 Process adapter with spray water cleaning



- The process adapter is mounted between the process connection of the measuring device and the application.
- Filtered water only should be used for spray water cleaning as otherwise the nozzles could clog.
- The amount of water needed is between 1 l/min (1 bar) and 3 l/min (6 bar).


#### Sensing weight for interface measurement in liquids with a significant difference in density

One of the following sensing weights can be used for interface measurement in liquids with a significant difference in density:

■ Order code:

71301873 Stainless steel 316Ti 71301875 Stainless steel 316Ti, coated

■ Weight: 4 kg



 $\blacksquare 24$  Sensing weight for HD interface measurement

The sensing weight can be easily replaced by releasing a screw.


#### Sensing weight for interface measurement in liquids with a minor difference in density

One of the following sensing weights can be used for interface measurement in liquids with a minor difference in density:

■ Order code:

71301876 Stainless steel 316Ti 71301877 Stainless steel 316Ti, coated

■ Weight: 4 kg



**■**25 Sensing weight for LD interface measurement

i

The sensing weight can be easily replaced by releasing a screw.

#### Chain to increase the block distance

The following chain can increase the block distance by a maximum distance of  $2\,\mathrm{m}$  in the event of longer connections which the sensing weight should not enter into:

Order code: 71301880Material: Stainless steel 316

Length: 2 mWeight: 0.3 kg


■ The chain can be shortened as required.

#### Devcie-specific tools

#### Removal tool

Using this puller tool and a 5 mm Allen key, the motor-gearbox-unit and tape spool can be removed easily for replacement.

Order code: 71001353Weight: 0.25 kg




■26 Removal tool

#### Tape stopper

Using the tape stopper and a 6 mm Allen key, the measuring tape can be secured inside the spool compartment, safeguarding against accidental roll-off when replacing the motor-gearbox-unit.

■ Order code: 71001352

■ Weight: 0.1 kg



■27 Tape stopper

#### **Documentation**



For an overview of the scope of the associated Technical Documentation, refer to the W@M Device Viewer: Enter the serial number from the nameplate (www.endress.com/deviceviewer)

#### Standard documentation

Operating Instructions for Silopilot FMM50 Documentation code: BA00286F

#### Supplementary devicedependent documentation

Safety Instructions ATEX
Documentation code: XA00425F

中国E+H技术销售 www.ainstru.com

电话: 18923830905 邮箱: sales@ainstru.com

